




396-2647Y1

John Deere 1990/N500C Series 500 Gal Tank Tower/PumpRight Mount


Air Seeder Manufacturer: John Deere
Kit Number: 515-03-201050





Parts List for SurePoint Tower/PumpRight Bracket

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	410-4454Y1	JD 1900/N500C Series Drill - Tower/PumpRight Mount Bracket for Cradle	1
2	380-1023	1/2" U-bolt Kit - fits 4" x 4" tube - (4" opening) includes flange nuts	2
3	384-1080	3/8" Hardware Kit - Carriage Bolts and Nuts	1
4	300-080108-5	1/2" x 1-1/2" Hex Head Bolt - G5	4
5	323-08	1/2" Flange Nut	4








Step by Step Instructions

1. Bolt the Tower/PumpRight mount to cradle frame using 1/2" U-bolts
- 2 A. Mount the SurePoint Tower electric pump to the front of the pump bracket with 3/8" carriage bolts (shown at right and below). Use 3/4" hose to feed Tower

OR

- 2 B. Mount the PumpRight hydraulic pump to the slotted holes on top of the pump bracket towards the end with 1/2" bolts (shown at right and bottom-right).



Related Items/Kits:

Tank Kit 551-03-100500 (Instruction Sheet 396-2622Y1)

Tank Kit 551-03-200100