




396-3195Y1

**Case iH Nutri-Tiller 940/950/955
24 Row—60' Wide**

Hitch Mounted Tank Instructions

CASE IH
AGRICULTURE


Kit Number: 516-02-100500






Parts List and Exploded View

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	420-3184Y1-BK	Case 940/950 Front Hitch Pedestal - Bolt Plate	2
2	420-3189Y1-BK	Case 940/950 Front Hitch Pedestal	2
3	300-100108-5	5/8" x 1-1/2" Hex Head Bolt - G5	8
4	323-10	5/8" Flange Nut - G5	8
5	330-10	5/8" Flat Washer - G5	8
6	300-120900-8	3/4" x 9" Hex Head Bolt - G8	8
7	330-12-8	3/4" Flat Washer - G8	8
8	331-12-8	3/4" Lock Washer - G8	8
9	320-12-8	3/4" Nut - G8	8




Step by Step Instructions

1. Position pedestals on each side of leveling bar gussets as shown, with hydraulic plumbing hoses routed through the center slot.
2. Loosely attach pedestals using 400-3184Y1 backer plate, 3/4" x 9" bolts, lock washer and flat washer.



3. Bolt tank cradle to pedestal using four (4) 5/8" x 1-1/2" hex head bolts, flat washer and flange nuts for each pedestal.
4. Check for tank for clearance and re-tighten tank straps after filling the tank.






General Dimensions SurePoint Catalyst™ 55 System

CATALYST

MICRO VOLUME APPLICATION SYSTEM






General Dimensions SurePoint Catalyst™ 110 System

CATALYST

MICRO VOLUME APPLICATION SYSTEM



General Dimensions SurePoint Accelerator Tanks

